



EASY REFERENCE PT CHART

°C	R22		R134A		R407C		R404A		R410A		R507A	
	kPa	psig	kPa	psig	kPa	psig	kPa	psig	kPa	psig	kPa	psig
20	814	118	469	68	778	113	990	143	1338	194	1023	148
22	866	126	505	73	832	121	1052	153	1419	206	1086	157
24	917	133	543	79	889	129	1117	162	1504	218	1151	167
26	975	141	582	84	948	137	1184	172	1592	231	1219	177
28	1040	151	623	90	1010	146	1254	182	1684	244	1290	187
30	1107	161	666	97	1074	156	1326	192	1779	258	1364	198
32	1165	169	711	103	1141	165	1402	203	1878	272	1440	209
34	1230	178	758	110	1211	176	1481	215	1981	287	1520	220
36	1300	189	807	117	1284	186	1562	226	2088	303	1602	232
38	1378	200	858	124	1360	197	1647	239	2199	319	1688	245
40	1448	210	911	132	1440	209	1735	252	2315	336	1777	258
42	1525	221	966	140	1522	221	1826	265	2434	353	1869	271
44	1610	233	1024	148	1607	233	1920	278	2558	371	1964	285
46	1688	245	1083	157	1696	246	2018	293	2686	389	2063	299
48	1770	257	1145	166	1789	259	2119	307	2819	409	2165	314
50	1855	269	1210	175	1885	273	2224	323	2956	429	2271	329
52	1950	283	1277	185	1984	288	2332	338	3099	449	2381	345
54	2050	297	1347	195	2087	303	2445	355	3245	470	2494	362
56	2140	310	1419	206	2194	318	2561	371	3397	492	2612	379
58	2245	326	1494	217	2305	334	2681	389	3554	515	2733	396
60	2345	340	1571	228	2420	351	2805	407	3716	539	2858	414

INFORMATION PROVIDED IS INTENDED AS A GUIDE ONLY. NO RESPONSIBILITY IS TAKEN BY THE PROVIDER FOR INCORRECT DATA.