


PANASONIC ROTARY WIRING DIAGRAM

MODEL	POWER INPUT watts	CURRENT Amps	CAPACITOR $\mu\text{f}/\text{V}$
2P14	705	3.3	30 μf
2P17	885	4.1	30 μf
2K22	1250	5.8	35 μf
2K28	1565	7.2	40 μf
2K32	1770	8.55	40 μf
2V36	1960	9.1	50 μf
2V42	2340	11	50 μf
2V49	2800	12.9	60 μf



ALL DIAGRAMS ARE INTENDED AS A GUIDE ONLY AND ARE TO BE USED ONLY BY A QUALIFIED ELECTRICAL TECHNICIAN. CIRCUMSTANCES IN THE FIELD MAY VARY AND AS SUCH NO RESPONSIBILITY IS TAKEN.